

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	7/22/2024	Time:	10:01 AM
Name of School Corporation:	AVON COMMUNITY SCHOOLS			Corp ID:	323315
Address of School Corporation:	7203 E HWY 36				
City:	Avon	Zip:	46123	County Number:	32
VIN:	1BAKJCSA0SF809702			Bus Number:	310
Make of Body:	Blue Bird Corporation	Year:	2024	Make of Chassis:	Blue Bird Corporation
Bus Type:	4			Year:	2025
Inspection Status:	O	Inspected By:	Joel Flores	PE:	7415

Comments:

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
7-1-3	Air leak at proper connection	Air leak at copper line from air dryer going into steel fitting, driver side near axle 1.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
7-2-9	There is any defect not in compliance with the minimum school bus brake inspection standards	Audible air leak, not at proper connection. Silver vale leaking air, near axle 2.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.