

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	2/21/2025	<b>Time:</b>	11:57 AM
<b>Name of School Corporation:</b>	SPENCER-OWEN COMMUNITY SCHOOLS			<b>Corp ID:</b>	606195
<b>Address of School Corporation:</b>	205 E Hillside				
<b>City:</b>	Spencer	<b>Zip:</b>	47460	<b>County Number:</b>	60
<b>VIN:</b>	4DRGVMMN5SB753006	<b>License Number:</b>	27448	<b>Bus Number:</b>	3
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2024	<b>Make of Chassis:</b>	IC Corporation
<b>Year:</b>	2024	<b>Year:</b>	2025		
<b>Bus Type:</b>	4	<b>Mileage:</b>	9899		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Mike Adams	<b>PE:</b>	7407

**Comments:**

### Violations - Rejected

Inspection Code Description Comments

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-4	Emergency door is not securely fastened to body
20-2-2	Door glass is missing
70-2-2	Any glass or glazing is cracked, chipped, clouded or distorted badly enough to prohibit a clear view from within the bus

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**