

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/1/2025	Time:	10:33 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	1BAKGCEA5JF337232		License Number:	14527	Bus Number:	27	
Make of Body:	Blue Bird Corporation	Year:	2016	Make of Chassis:	Blue Bird Corporation	Year:	2018
Bus Type:	4			Mileage:	105287		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Comments:

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>	<u>Comments</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle	Missing from the left front window
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired	Holes in seat back: 2 forward of left rear emergency exit
17-1-1	Any dome light is inoperative	Right front and third from front on the left

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.