

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual **Date:** 1/17/2012 **Time:** 11:35 AM
Name of School Corporation: FRANKFORT COMMUNITY SCHOOLS **Corp ID:** 121170
Address of School Corporation: 50 S Maish Rd
City: Frankfort **Zip:** 46041 **County Number:** 12
VIN: 1HVBGAAP6VA079059 **License Number:** 15279 **Bus Number:** 24
Make of Body: AmTran **Year:** 1997 **Make of Chassis:** IC Corporation **Year:** 1997
Bus Type: D **Mileage:** Unknown
Inspection Status: R **Inspected By:** Joel Flores **PE:** 7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Power steering unit leaks at any point.
34-1-2	The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.).
34-1-1	There is significant engine oil or fluid leak from the engine.
37-1-1	The bus body has rust or rusted through areas which may weaken the body.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.