REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Semi-AnnualDate:1/17/2012Time:11:35 AMName of School Corporation:FRANKFORT COMMUNITY SCHOOLSCorp ID:121170

Address of School Corporation: 50 S Maish Rd

City:FrankfortZip:46041County Number:12VIN:1HVBGAAP6VA079059License Number:15279Bus Number:24Make of Body:AmTran Year:1997Make of Chassis:IC Corporation Year:1997

Bus Type: D Mileage: Unknown

Inspection Status: R Inspected By: Joel Flores PE: 7415

Violations - Rejected

Inspection Code	<u>Description</u>
68-1-1	Power steering unit leaks at any point.
34-1-2	The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.).
34-1-1	There is significant engine oil or fluid leak from the engine.
37-1-1	The bus body has rust or rusted through areas which may weaken the body.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.