

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Semi-Annual Date: 1/17/2012 Time: 10:39 AM  
Name of School Corporation: FRANKFORT COMMUNITY SCHOOLS Corp ID: 121170  
Address of School Corporation: 50 S Maish Rd  
City: Frankfort Zip: 46041 County Number: 12  
VIN: 1HVBGAAP4VA079058 License Number: 15278 Bus Number: 23  
Make of Body: AmTran Year: 1997 Make of Chassis: IC Corporation Year: 1997  
Bus Type: D Mileage: Unknown  
Inspection Status: R Inspected By: Joel Flores PE: 7415

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-4	There is a significant fluid leak from the transmission.
34-1-2	The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.).
34-1-1	There is significant engine oil or fluid leak from the engine.
68-1-1	Power steering unit leaks at any point.

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.