REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:1/17/2012 Time:3:49 PM

Name of School Corporation: EAST GIBSON SCHOOL CORPORATION Corp ID: 262725

Address of School Corporation: 941 S Franklin St

City:Oakland CityZip:47660County Number:26VIN:1GB6G3AG8A1145550License Number:2370Bus Number:21Make of Body:Star Trans Year:2010Make of Chassis:ChevroletYear:2010

Bus Type: Mileage: Unknown

Inspection Status: A Inspected By: Roger Cannon PE: 5063

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description