## REPORT OF SCHOOL BUS INSPECTION

| Type of<br>Inspection:                                     | Semi-Annual                 |   |                  | Date:               | 1/18/2012 | Time:             | 10:54<br>AM |
|--|-----------------------------|---|------------------|---------------------|-----------|-------------------|-------------|
| Name of School Corporation: Address of School Corporation: |                             | CONCORD COMMUNITY SCHOOLS 59040 Minuteman Way |                  |                     | Corp ID:  | 202270            |             |
| City:  | Elkhart                     |   | Zip:             | 46517               |           | County<br>Number: | 20          |
| VIN:   | 1T75T3B20V1148392           |   |                  | License<br>Number:  | 15136     | Bus Number:       | 41          |
| Make of Body:  | Thomas Built Buses,<br>Inc. | Year:   | : 1997           | Make of<br>Chassis: | Ford      | Year:             | 1997        |
| Bus Type:  | D                           |   |                  | Mileage:            | Unknown   |                   |             |
| Inspection Status  | : O                         |   | Inspected<br>By: | Travis Harrold      |           | PE:               | 8022        |

**Violations - Rejected** 

**Inspection Code Description** 

## **Violations - Out of Service**

| <u>inspection</u><br><u>Code</u> | <u>Description</u>  |
|----------------------------------|---|
| 14-2-6                           | There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely. |

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.