

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	2/1/2012	<b>Time:</b>	10:27 AM
<b>Name of School Corporation:</b>	M.S.D. LAWRENCE TOWNSHIP	<b>Corp ID:</b>	495330		
<b>Address of School Corporation:</b>	5850 Thunderbird Rd				
<b>City:</b>	Indianapolis	<b>Zip:</b>	46236	<b>County Number:</b>	49
<b>VIN:</b>	1T88N3B2231121369	<b>License Number:</b>	18870	<b>Bus Number:</b>	177
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2003	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Amy Gaul	<b>PE:</b>	5934

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
83-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.
14-2-3	The required low air-pressure warning device fails to operate properly

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**