

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                             |                        |             |                         |                          |
|---------------------------------------|-----------------------------|------------------------|-------------|-------------------------|--------------------------|
| <b>Type of Inspection:</b>            | Annual                      | <b>Date:</b>           | 1/27/2012   | <b>Time:</b>            | 10:04 AM                 |
| <b>Name of School Corporation:</b>    | DECATUR COUNTY COMM. SCHOOL |                        |             | <b>Corp ID:</b>         | 161655                   |
| <b>Address of School Corporation:</b> | 1645 W SR 46                |                        |             |                         |                          |
| <b>City:</b>                          | Greensburg                  | <b>Zip:</b>            | 47240       | <b>County Number:</b>   | 16                       |
| <b>VIN:</b>                           | 1GDL7T1P9WJ512053           | <b>License Number:</b> | B158D       | <b>Bus Number:</b>      | 34                       |
| <b>Make of Body:</b>                  | GMC                         | <b>Year:</b>           | 1998        | <b>Make of Chassis:</b> | Thomas Built Buses, Inc. |
| <b>Bus Type:</b>                      | C                           | <b>Mileage:</b>        | Unknown     | <b>Year:</b>            | 1998                     |
| <b>Inspection Status:</b>             | R                           | <b>Inspected By:</b>   | Chris Clark | <b>PE:</b>              | 6665                     |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                                                                  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| 27-1-2                 | The drive shaft has excessive up and down, or side to side movement at any universal joint or carrier bearing.                                      |
| 36-1-3                 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 66-1-5                 | Upholstery or padding is ripped, torn, or improperly repaired.                                                                                      |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**