REPORT OF SCHOOL BUS INSPECTION

Type of 9:06 Post-Crash Inspection Date: 2/14/2012 Time: Inspection: AM LAPORTE COMMUNITY SCHOOL CORP. Corp ID: 464945 Name of School Corporation: **Address of School Corporation:** 1921 A St County City: La Porte Zip: 46350 46 Number: License VIN: IT7YT4C2981101318 31195 Bus Number: 85 Number: Thomas Built Buses, Year: 2008 Thomas Built Buses, Year: Make of Make of Body: 2008 Chassis: Inc. **Bus Type:** D Mileage: Unknown Inspection Inspected R PE: David Eggers 5191 Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

Any seat is loose from the floor or seat rail.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.