REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	2/16/2012	**Time:**	9:07 AM
Name of School Corporation:	SCOTT COUNTY SCHOOL DISTRICT 1			**Corp ID:**	727230
Address of School Corporation:	US 31 S				
City:	Austin	**Zip:**	47102	**County Number:**	72
VIN:	4DRBUAAP1BB280724	**License Number:**	74203	**Bus Number:**	7
Make of Body:	IC Corporation **Year:** 2011	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Troy Boyd	**PE:**	5171

Violations - Rejected

Inspection Code	Description
33-1-1	Any belt is badly chaffed, cracked, broken or missing.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.