

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 2/23/2012 **Time:** 8:04 AM
Name of School Corporation: EAST ALLEN COUNTY SCHOOLS **Corp ID:** 20255
Address of School Corporation: 1322 Green Rd
City: New Haven **Zip:** 46774 **County Number:** 2
VIN: 4DRBUSKN7CB629129 **License Number:** 2457 **Bus Number:** 117
Make of Body: IC Corporation **Year:** 2012 **Make of Chassis:** IC Corporation **Year:** 2012
Bus Type: C **Mileage:** Unknown
Inspection Status: R **Inspected By:** Tom Merkling **PE:** 5390

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.