

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	2/29/2012	<b>Time:</b>	11:23 AM
<b>Name of School Corporation:</b>	M.S.D. WARREN TWP.	<b>Corp ID:</b>	495360		
<b>Address of School Corporation:</b>	9150 Rawles				
<b>City:</b>	Indianapolis	<b>Zip:</b>	46229	<b>County Number:</b>	49
<b>VIN:</b>	1T7YT4C2561271253	<b>License Number:</b>	20996	<b>Bus Number:</b>	41
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2006	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Chris Kath	<b>PE:</b>	6690

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
76-1-2	Any shock absorber is leaking fluid

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
99-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

### Bus Type Description

**Type D School Bus** – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.