

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 2/29/2012	<b>Time:</b> 10:48 AM
<b>Name of School Corporation:</b> M.S.D. WARREN TWP.	<b>Corp ID:</b> 495360	
<b>Address of School Corporation:</b> 9150 Rawles		
<b>City:</b> Indianapolis	<b>Zip:</b> 46229	<b>County Number:</b> 49
<b>VIN:</b> 1BABNCKA05F224904	<b>License Number:</b> 20241	<b>Bus Number:</b> 25
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2005	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Bus Type:</b> D	<b>Mileage:</b> Unknown	<b>Year:</b> 2005
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chris Kath	<b>PE:</b> 6690

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
53-1-1	A heater motor is inoperative at any speed.
76-1-1	There are any loose, broken, or missing mountings
34-1-4	There is a significant fluid leak from the transmission.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-2	Any push-rod travel measures 1/4 inch or more beyond the readjustment limit, or if any two (2) brakes measure less than 1/4 inch beyond the readjustment limit.
36-2-1	Exhaust leak occurs in the exhaust system prior to the muffler outlet.
37-2-2	Any body surface protrudes beyond the normal limits of the body structure.

### Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**