

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 3/2/2012 **Time:** 8:36 AM
Name of School Corporation: MERRILLVILLE COMM. SCHOOL CORP **Corp ID:** 454600
Address of School Corporation: 6601 Delaware St
City: Merrillville **Zip:** 46410 **County Number:** 45
VIN: 4DRBRAAP34B974688 **License Number:** 7792 **Bus Number:** 90
Make of Body: IC Corporation **Year:** 2004 **Make of Chassis:** IC Corporation **Year:** 2004
Bus Type: C **Mileage:** Unknown
Inspection Status: O **Inspected By:** Nathan Sherer **PE:** 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-2	Any seat back or bottom is loose.
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
53-1-1	A heater motor is inoperative at any speed.
39-1-3	Not fully charged
39-1-5	Not securely mounted.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.