

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/2/2012	Time:	1:50 PM		
Name of School Corporation:	FRANKLIN COMM. SCHOOL CORP.			Corp ID:	414225		
Address of School Corporation:	750 E SR 44						
City:	Franklin	Zip:	46131	County Number:	41		
VIN:	4DRBUAAN89B681471		License Number:	32199	Bus Number:	111	
Make of Body:	IC Corporation	Year:	2009	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	John Pang	PE:	6196		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
96-1-2	Rims are bent or loose
10-1-7	Battery compartment door is not securely fastened.
10-1-3	Any battery is loose in its mounting.
55-1-2	The horn is not audible.
52-1-1	Any headlight is inoperative.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
85-2-5	There are no OOS criteria for the optional school bus crossing arm
18-2-1	The front or rear bumper is missing, torn, loose or altered from original specifications.
76-2-1	Any shock absorber is broken or missing
81-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
81-2-3	Any steering component jams or inhibits safe movement
81-2-2	There is pitman arm movement on output shaft
10-2-2	Wiring is exposed.
91-2-3	Any tire is flat
14-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
37-2-1	There is body damage which could cause injury to persons near the bus (i.e. jagged metal edges, etc.).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.