REPORT OF SCHOOL BUS INSPECTION

Type of 11:13 Annual 3/12/2012 **Time**: Date: Inspection: AM OUR LADY OF GREENWOOD Name of School Corporation: 41B353 Corp ID: **Address of School Corporation:** 399 S Meridian St County City: Greenwood Zip: 46142 41 Number: License VIN: 1GDL7T1P0VJ513784 b514d **Bus Number:** Number: Make of Blue Bird **Year:** 1997 GMC Make of Body: Year: 1997 Corporation Chassis: **Bus Type:** С Mileage: Unknown Inspected PE: **Inspection Status:** R John Pang 6196 By:

Violations - Rejected

Inspection Code	<u>Description</u>
66-1-1	Any seat is loose from the floor or seat rail.
76-1-1	There are any loose, broken, or missing mountings
34-1-4	There is a significant fluid leak from the transmission.
34-1-1	There is significant engine oil or fluid leak from the engine.
96-1-1	Rims and wheels are painted any other color than those specified above

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.