REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/13/2012	**Time:**	5:26 PM
Name of School Corporation:	NORTH DAVIESS CO. COMM. SCHOOL			**Corp ID:**	141375
Address of School Corporation:	5494 E SR 58				
City:	Elnora	**Zip:**	47529	**County Number:**	14
VIN:	1HVBBABP1YH283633	**License Number:**	6382	**Bus Number:**	ND3
Make of Body:	AmTran **Year:** 2000	**Make of Chassis:**	IC Corporation	**Year:**	2000
Bus Type:	C	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	Kelly Hammond	**PE:**	6682

Violations - Rejected

Inspection Code	Description
55-1-4	Required horn(s) are not present.
97-1-1	Washers do not function properly in any manner

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.