## REPORT OF SCHOOL BUS INSPECTION

Type of Annual 3/13/2012 **Time**: Date: 5:21 PM Inspection: Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL 141375 Corp ID: **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: 1BAKFCKH25F229144 B896D **Bus Number:** 18 Number: Make of Blue Bird Chevrolet Year: Year: 2005 Make of Body: 2005 Corporation Chassis: **Bus Type:** С Mileage: Unknown Inspected PE: 6682 Inspection Status: R Kelly Hammond By:

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

90-1-2 One (1) taillight or one (1) brake light does not function

97-1-1 Washers do not function properly in any manner

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.