

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/14/2012	Time:	10:07 AM		
Name of School Corporation:	CENTER GROVE COMM. SCHOOL CORP			Corp ID:	414205		
Address of School Corporation:	4900 W Stones Crossing Rd						
City:	Greenwood	Zip:	46143	County Number:	41		
VIN:	4DRBWAAR5AA167679	License Number:	32716	Bus Number:	6		
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2010
Bus Type:	D	Mileage:	Unknown				
Inspection Status:	O	Inspected By:	John Pang	PE:	6196		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	There is significant engine oil or fluid leak from the engine.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
85-2-4	Stop arm does not function properly

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.