REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	3/14/2012	**Time:**	11:11 AM
Name of School Corporation:	CENTER GROVE COMM. SCHOOL CORP			**Corp ID:**	414205
Address of School Corporation:	4900 W Stones Crossing Rd				
City:	Greenwood	**Zip:**	46143	**County Number:**	41
VIN:	4DRBJABN33A945619	**License Number:**	6447	**Bus Number:**	58
Make of Body:	IC Corporation **Year:** 2003	**Make of Chassis:**	IC Corporation	**Year:**	2003
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	O	**Inspected By:**	Chris Kath	**PE:**	6690

Violations - Rejected

Inspection Code	Description
34-1-1	There is significant engine oil or fluid leak from the engine.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.