

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/15/2012	Time:	11:23 AM		
Name of School Corporation:	CENTER GROVE COMM. SCHOOL CORP			Corp ID:	414205		
Address of School Corporation:	4900 W Stones Crossing Rd						
City:	Greenwood	Zip:	46143	County Number:	41		
VIN:	4DRBWAFN25A983499		License Number:	21083	Bus Number:	78	
Make of Body:	IC Corporation	Year:	2005	Make of Chassis:	IC Corporation	Year:	2005
Bus Type:	D			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	John Pang	PE:	6196		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-4	There is a significant fluid leak from the transmission.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
14-2-6	There is any defect which the inspector feels would adversely affect the ability of the vehicle to stop safely.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.