

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 3/16/2012 Time: 9:43 AM
Name of School Corporation: MERRILLVILLE COMM. SCHOOL CORP Corp ID: 454600
Address of School Corporation: 6601 Delaware St
City: Merrillville Zip: 46410 County Number: 45
VIN: 4DRBUAAN77B380168 License Number: 75131 Bus Number: 26
Make of Body: IC Corporation Year: 2006 Make of Chassis: IC Corporation Year: 2006
Bus Type: C Mileage: Unknown
Inspection Status: R Inspected By: Nathan Sherer PE: 7029

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
37-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.
18-1-1	The front bumper does not extend to the edge of the fenders.
63-1-1	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.