

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 3/19/2012 **Time:** 10:54 AM
Name of School Corporation: CENTER GROVE COMM. SCHOOL CORP **Corp ID:** 414205
Address of School Corporation: 4900 W Stones Crossing Rd
City: Greenwood **Zip:** 46143 **County Number:** 41
VIN: 1GBJG312561238385 **License Number:** 84490 **Bus Number:** 207
Make of Body: Mid Bus, Inc. **Year:** 2007 **Make of Chassis:** Chevrolet **Year:** 2007
Bus Type: **Mileage:** Unknown
Inspection Status: **Inspected By:** John Pang **PE:** 6196

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

81-2-5 There is movement in a spring loaded drag link greater than 1/8 inch

Bus Type Description