

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/19/2012	Time:	11:51 AM		
Name of School Corporation:	EAST ALLEN COUNTY SCHOOLS			Corp ID:	20255		
Address of School Corporation:	1322 Green Rd						
City:	New Haven	Zip:	46774	County Number:	2		
VIN:	4DRBVAAN36A295507		License Number:	21351	Bus Number:	5	
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation	Year:	2006
Bus Type:	D			Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Tom Merkling	PE:	5390		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
66-1-2	Any seat back or bottom is loose.
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.