REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Date: 3/20/2012 Time: 11:49 AM

Name of School Corporation: DELAWARE COMM. SCHOOL CORP. Corp ID: 181875

Address of School Corporation: 7821 SR 3 N

City:MuncieZip:47303County Number:18VIN:4DRAPSKH7CB591740License Number:5559Bus Number:3Make of Body:IC Corporation Year:2012Make of Chassis:IC Corporation Year:2012

Bus Type: Mileage: Unknown

Inspection Status: A Inspected By: Brian Bills PE: 5506

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description