

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/21/2012	<b>Time:</b> 9:06 AM
<b>Name of School Corporation:</b> ELWOOD COMMUNITY SCHOOL CORP.	<b>Corp ID:</b> 485280	
<b>Address of School Corporation:</b> 1306 N Anderson St		
<b>City:</b> Elwood	<b>Zip:</b> 46036	<b>County Number:</b> 48
<b>VIN:</b> 4DRBUSKP4AB185352	<b>License Number:</b> 33041	<b>Bus Number:</b> 4
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2010	<b>Make of Chassis:</b> IC Corporation
<b>Year:</b> 2010	<b>Mileage:</b> Unknown	<b>Year:</b> 2010
<b>Bus Type:</b> B		
<b>Inspection Status:</b> A	<b>Inspected By:</b> Dave Whiting	<b>PE:</b> 6480

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.