

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/28/2012	<b>Time:</b> 8:43 AM
<b>Name of School Corporation:</b> IMPACT INSTITUTE	<b>Corp ID:</b> 220001	
<b>Address of School Corporation:</b> 1607 Dowling Street		
<b>City:</b> Kendallville	<b>Zip:</b> 46755	<b>County Number:</b> 17
<b>VIN:</b> 1GDHGX1R3X1057466	<b>License Number:</b> 7809	<b>Bus Number:</b> 3
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 1999	<b>Make of Chassis:</b> GMC
<b>Bus Type:</b> A1	<b>Mileage:</b> Unknown	<b>Year:</b> 1999
<b>Inspection Status:</b> R	<b>Inspected By:</b> Tom Merkling	<b>PE:</b> 5390

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
76-1-2	Any shock absorber is leaking fluid
30-1-3	The handle guard is missing or bent.
32-1-1	The reflective tape is applied in the wrong location, is missing, wrong width or badly faded.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**