

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/28/2012	Time:	8:43 AM
Name of School Corporation:	IMPACT INSTITUTE	Corp ID:	220001		
Address of School Corporation:	1607 Dowling Street				
City:	Kendallville	Zip:	46755	County Number:	17
VIN:	1GDHG31R3X1057466	License Number:	7809	Bus Number:	3
Make of Body:	Thomas Built Buses, Inc.	Year:	1999	Make of Chassis:	GMC
Year:	1999	Year:	1999	Year:	1999
Bus Type:	A1	Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Tom Merkling	PE:	5390

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
76-1-2	Any shock absorber is leaking fluid
30-1-3	The handle guard is missing or bent.
32-1-1	The reflective tape is applied in the wrong location, is missing, wrong width or badly faded.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.