

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/30/2012	<b>Time:</b>	12:09 PM
<b>Name of School Corporation:</b>	GARRETT-KEYSER-BUTLER COMM SCH			<b>Corp ID:</b>	171820
<b>Address of School Corporation:</b>	801 E Houston St				
<b>City:</b>	Garrett	<b>Zip:</b>	46738	<b>County Number:</b>	17
<b>VIN:</b>	1BAKFCKA97F241636	<b>License Number:</b>	30179	<b>Bus Number:</b>	6
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Tom Merklng	<b>PE:</b>	5390

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
32-1-1	The reflective tape is applied in the wrong location, is missing, wrong width or badly faded.
34-1-4	There is a significant fluid leak from the transmission.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
85-2-3	Stop arm does not fully extend to a right angle to the bus

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**