REPORT OF SCHOOL BUS INSPECTION

Type of 9:00 Time: Annual Date: 4/3/2012 Inspection: AM Name of School Corporation: CROWN POINT COMM. SCHOOL CORP. 454660 Corp ID: **Address of School Corporation:** 1151 E Summit County City: Crown Point Zip: 46307 45 Number: License VIN: 4UZAAXCS25CM97125 19917 **Bus Number:** 54 Number: Make of Thomas Built Buses, Year: 2004 Make of Body: Freightliner Year: 2004 Inc. Chassis: Bus Type: С Mileage: Unknown Inspected PE: 7029 **Inspection Status:** R Nathan Sherer By:

Violations - Rejected

Inspection Code Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

<u>Inspection Code Description</u>

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.