## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	4/4/2012	Time:	11:53 AM
Name of School Co	orporation: EAST	ALLEN COUN	TY SCHOOLS		Corp ID:	20255
Address of School	Corporation:	1322 Green Ro	ł			
City:	New Haven	Zip:	46774		<b>County Number:</b>	2
VIN:	4DRBUAFN95B9794	17	License Number:	7334	Bus Number:	124
Make of Body:	IC Corporation Year:	2005	Make of Chassis:	IC Corporation	Year:	2005
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Tom Merkling		PE:	5390

## **Violations - Rejected**

Inspection Code	<b>Description</b>
76-1-2	Any shock absorber is leaking fluid

## Violations - Out of Service

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.