

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	4/4/2012	<b>Time:</b>	9:09 AM
<b>Name of School Corporation:</b>	CROWN POINT COMM. SCHOOL CORP.	<b>Corp ID:</b>	454660		
<b>Address of School Corporation:</b>	1151 E Summit				
<b>City:</b>	Crown Point	<b>Zip:</b>	46307	<b>County Number:</b>	45
<b>VIN:</b>	4UZAAXCS95CM97123	<b>License Number:</b>	19927	<b>Bus Number:</b>	52
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2004	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	Unknown		
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Nathan Sherer	<b>PE:</b>	7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
66-1-1	Any seat is loose from the floor or seat rail.

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**