

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/5/2012	Time: 8:19 AM
Name of School Corporation: M.S.D. STEUBEN COUNTY	Corp ID: 767615	
Address of School Corporation: 400 S Martha St		
City: Angola	Zip: 46703	County Number: 76
VIN: 4UZABRCS87CX41176	License Number: 15963	Bus Number: 111
Make of Body: Thomas Built Buses, Inc.	Year: 2007	Make of Chassis: Freightliner
Year: 2007	Mileage: Unknown	Year: 2007
Bus Type: C		
Inspection Status: R	Inspected By: Tom Merkling	PE: 5390

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	The first aid kit is not properly filled in accordance with the '24 Unit Kit'.
93-1-4	Any front turn signal does not function properly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.