

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/11/2012	Time: 10:25 AM
Name of School Corporation: SOUTH DEARBORN COMM. SCH. CORP	Corp ID: 151600	
Address of School Corporation: 6109 Squire Place		
City: Aurora	Zip: 47001	County Number: 15
VIN: 1HVBBABP75H686572	License Number: B424F	Bus Number: 3A
Make of Body: Thomas Built Buses, Inc.	Year: 1995	Make of Chassis: IC Corporation
Year: 1995	Mileage: Unknown	Year: 1995
Bus Type: D		
Inspection Status: O	Inspected By: Chris Clark	PE: 6665

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
52-1-1	Any headlight is inoperative.
90-1-2	One (1) taillight or one (1) brake light does not function
99-1-1	There is unapproved glazing material installed in the bus

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
16-2-1	The master cylinder is leaking at any point.

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.