REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/13/2012	Time:	10:44 AM
Name of School Address of Scho	•	HANOVER COM PO Box 64	IM. SCHOOL CO 15	RP.	Corp ID:	454580
City:	Cedar Lake	Zip:	46303		County Number:	45
VIN:	1HVBBABN84H581279		License Number:	4706	Bus Number:	11
Make of Body:	Blue Bird Corporation	Year : 2004	Make of Chassis:	Blue Bird Corporation	Year:	2004
Bus Type:	С		Mileage:	Unknown		
Inspection Status:	0	Inspected By:	Nathan Shere	er	PE:	7029

Violations - Rejected

Inspection Code	<u>Description</u>
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
36-1-5	Any hanger, clamp or bracket is missing, loose or broken.

Violations - Out of Service

Inspection Code	<u>Description</u>
36-2-1	Exhaust leak occurs in the exhaust system prior to the muffler outlet.

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.