## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	4/13/2012	Time:	9:23 AM
Name of School Address of School	Corporation: H.	ANOVER COMM PO Box 645		RP.	Corp ID:	454580
City:	Cedar Lake	Zip:	46303		County Number:	45
VIN:	1T88U3C2961272280		License Number:	6471	Bus Number:	18
Make of Body:	Thomas Built Buses, You	ear: 2006	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2006
Bus Type:	D		Mileage:	Unknown		
Inspection Status:	0	Inspected By:	Nathan Sherer		PE:	7029

## **Violations - Rejected**

Inspection Code	<u>Description</u>
39-1-3	Not fully charged
26-1-1	Any dome light is inoperative.

## **Violations - Out of Service**

Inspection Code	<u>Description</u>
14-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement.
14-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking.
46-2-1	There is a fuel leak from any line, connection or fitting.
36-2-1	Exhaust leak occurs in the exhaust system prior to the muffler outlet.
99-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.