REPORT OF SCHOOL BUS INSPECTION

8:09 Type of Time: Annual Date: 4/13/2012 Inspection: AM Name of School Corporation: HANOVER COMM. SCHOOL CORP. 454580 Corp ID: **Address of School Corporation:** PO Box 645 County City: Cedar Lake Zip: 46303 45 Number: License VIN: 1HVBBABN8EH550578 9246 Bus Number: Number: Make of Blue Bird Blue Bird Year: 2002 Make of Body: Year: 2002 Corporation Chassis: Corporation

Mileage:

Bus Type: С

Inspection Inspected 0 Status: By:

Nathan Sherer

Unknown

PE: 7029

Violations - Rejected

Inspection Code	<u>Description</u>
90-1-2	One (1) taillight or one (1) brake light does not function
	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in an

Any exnaust leak can be felt with the bare hand six (6) inches from the leak in any 36-1-3

direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description 85-2-1 Any stop arm light is inoperative

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.