REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 4/25/2012 Time: 11:00 AM

Name of School Corporation: OAK HILL UNITED SCHOOL CORP. Corp ID: 525625

Address of School Corporation: PO Box 550

City:ConverseZip:46919County Number:52VIN:4DRBUSKN69B095307License Number:30874Bus Number:22Make of Body:IC Corporation Year:2009
Make of Chassis: IC Corporation Year:

Bus Type: C Mileage: Unknown

Inspection Status: R Inspected By: Randy McPike PE: 7018

Violations - Rejected

Inopostion

<u>Inspection</u> <u>Code</u>	<u>Description</u>
99-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
62-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative.
10-1-3	Any battery is loose in its mounting.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.