

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/25/2012	Time:	9:37 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	1HVBBAAN12H530897		License Number:	1115	Bus Number:	3	
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	IC Corporation	Year:	2002
Bus Type:	C			Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
79-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
36-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.