

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	4/25/2012	Time:	2:05 PM		
Name of School Corporation:	TRI-CAP EOC, INC	Corp ID:	19001Z				
Address of School Corporation:	PO Box 729						
City:	Jasper	Zip:	47546	County Number:	19		
VIN:	1GBHG31R8W1089739	License Number:	16334	Bus Number:	7		
Make of Body:	Mid Bus, Inc.	Year:	1998	Make of Chassis:	Chevrolet	Year:	1998
Bus Type:	A1	Mileage:	Unknown				
Inspection Status:	O	Inspected By:	Roger Cannon	PE:	5063		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
21-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative.
90-1-2	One (1) taillight or one (1) brake light does not function

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
85-2-1	Any stop arm light is inoperative

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.