

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|------------------------------|------------------------|--------------|-------------------------|--------------|--------------|------|
| Type of Inspection: | Re-Inspection | Date: | 4/26/2012 | Time: | 10:34 AM | | |
| Name of School Corporation: | OAK HILL UNITED SCHOOL CORP. | | | Corp ID: | 525625 | | |
| Address of School Corporation: | PO Box 550 | | | | | | |
| City: | Converse | Zip: | 46919 | County Number: | 52 | | |
| VIN: | 4UZAAXBV72CJ95823 | License Number: | 1124 | Bus Number: | 6 | | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2002 | Make of Chassis: | Freightliner | Year: | 2002 |
| Bus Type: | B | Mileage: | Unknown | | | | |
| Inspection Status: | A | Inspected By: | Randy McPike | PE: | 7018 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.