

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/26/2012	Time:	10:00 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	1HVBBABN04H579865	License Number:	19630	Bus Number:	9
Make of Body:	Blue Bird Corporation	Year:	2004	Make of Chassis:	IC Corporation
Bus Type:	C	Mileage:	Unknown		
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
53-1-1	A heater motor is inoperative at any speed.
79-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
99-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.