

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection Date: 4/26/2012 Time: 8:33 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP. Corp ID: 525625
Address of School Corporation: PO Box 550
City: Converse Zip: 46919 County Number: 52
VIN: 4DRBUAFN35B974939 License Number: 20406 Bus Number: 23
Make of Body: IC Corporation Year: 2005 Make of Chassis: IC Corporation Year: 2005
Bus Type: C Mileage: Unknown
Inspection Status: O Inspected By: Randy McPike PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
92-1-4	The trash container is not located in the driver's area

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.