REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/27/2012	**Time:**	9:26 AM
Name of School Corporation:	CARMEL CLAY SCHOOLS			**Corp ID:**	293060
Address of School Corporation:	5185 E 131st St				
City:	Carmel	**Zip:**	46032	**County Number:**	29
VIN:	4DRBWAARXAA185174	**License Number:**	32803	**Bus Number:**	104
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2010
Bus Type:	D	**Mileage:**	Unknown		
Inspection Status:	R	**Inspected By:**	John Pang	**PE:**	6196

Violations - Rejected

Inspection Code	Description
34-1-1	There is significant engine oil or fluid leak from the engine.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.