# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Spot Checks | **Date:** | 4/27/2012 | **Time:** | 8:30 AM |
| **Name of School Corporation:** | LOGANSPORT COMM. SCHOOL CORP. | | | **Corp ID:** | 90875 |
| **Address of School Corporation:** | 2829 George St | | | | |
| **City:** | Logansport | **Zip:** | 46947 | **County Number:** | 9 |
| **VIN:** | 4DRBRABP23B947401 | **License Number:** | 114 | **Bus Number:** | 206 |
| **Make of Body:** | IC Corporation **Year:** 2003 | **Make of Chassis:** | IC Corporation | **Year:** | 2003 |
| **Bus Type:** | C | **Mileage:** | Unknown | | |
| **Inspection Status:** | R | **Inspected By:** | Randy McPike | **PE:** | 7018 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 41-1-2 | The first aid kit is not properly filled in accordance with the '24 Unit Kit'. |
| 34-1-1 | There is significant engine oil or fluid leak from the engine. |
| 55-1-2 | The horn is not audible. |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**