

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/1/2012	Time:	1:00 PM
Name of School Corporation:	M.S.D. SOUTHWEST ALLEN COUNTY			Corp ID:	20125
Address of School Corporation:					
City:		Zip:		County Number:	2
VIN:	1BABNCPA77F244417	License Number:	5082	Bus Number:	7
Make of Body:	Blue Bird Corporation	Year:	2007	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	Unknown	Year:	2007
Inspection Status:	O	Inspected By:	Tom Merkling	PE:	5390

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
37-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.