## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/7/2012 Time:2:21 PMName of School Corporation: MARQUETTE HIGH SCHOOLCorp ID:71002Z

Address of School Corporation: 306 W 10th St.

City:Michigan CityZip:46306County Number: 46VIN:1GBHG31R6Y1201361License Number: b872aaBus Number: 1Make of Body:Chevrolet Year: 2000Make of Chassis: CorbeilYear: 2000

Bus Type: Mileage: Unknown

Inspection Status: O Inspected By: Nathan Sherer PE: 7029

#### **Violations - Rejected**

# Inspection CodeDescription30-1-8If required, positive door opening device is missing or fails to operate properly.91-1-3Any rear tire has less than 2/32 inch tread depth

41-1-2 The first aid kit is not properly filled in accordance with the '24 Unit Kit'.

#### **Violations - Out of Service**

### <u>Inspection Code</u> <u>Description</u>

15-2-1 There is no brake certification, the certification has expired or is not signed.

#### **Bus Type Description**