

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 5/7/2012      **Time:** 2:51 PM  
**Name of School Corporation:** MARQUETTE HIGH SCHOOL      **Corp ID:** 71002Z  
**Address of School Corporation:** 306 W 10th St.  
**City:** Michigan City      **Zip:** 46306      **County Number:** 46  
**VIN:** 1HVBBABP2TH372720      **License Number:** 3180      **Bus Number:** 1  
**Make of Body:** AmTran      **Year:** 1996      **Make of Chassis:** AmTran      **Year:** 1996  
**Bus Type:** C      **Mileage:** Unknown  
**Inspection Status:** O      **Inspected By:** Nathan Sherer      **PE:** 7029

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
37-1-5	Any paint is badly faded or peeling.
37-1-1	The bus body has rust or rusted through areas which may weaken the body.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
36-2-1	Exhaust leak occurs in the exhaust system prior to the muffler outlet.
53-2-2	Any fluid leaks from the heater or hoses into the bus interior.

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**